

CUSTOMER SERVICE BULLETIN

Radio Shack® CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	4532-01
Description	SCRIPSIT Utilities
Model	Model II/12
Stock No.	26-4532 Version 01.00.00
Date	April 19, 1984
Page 1 of	1

Problem

The following patches will change the communications from port A to port B for SCRIPSIT 2.1 Utilities.

* * THE FOLLOWING PATCHES ARE OPTIONAL! * *

Solution

These PATCHES must be made BEFORE installing the utilities.

```
PATCH SCRIPSIT/XMT {A=8E37,F=60,C=62}
PATCH SCRIPSIT/XMT {A=8EB2,F=60,C=62}
PATCH SCRIPSIT/XMT {A=EDA3,F=60,C=62}
PATCH SCRIPSIT/XMT {A=EDE6,F=60,C=62}
PATCH SCRIPSIT/XMT {A=EE1F,F=60,C=62}
PATCH SCRIPSIT/XMT {A=EF31,F=60,C=62}
PATCH SCRIPSIT/XMT {A=EF67,F=60,C=62}
PATCH SCRIPSIT/XMT {A=89E4,F=60,C=62}
PATCH SCRIPSIT/XMT {A=8E29,F=61,C=63}
PATCH SCRIPSIT/XMT {A=8E92,F=61,C=63}
PATCH SCRIPSIT/XMT {A=EDA0,F=61,C=63}
PATCH SCRIPSIT/XMT {A=EDDB,F=61,C=63}
PATCH SCRIPSIT/XMT {A=EE24,F=61,C=63}
PATCH SCRIPSIT/XMT {A=EEC2,F=61,C=63}
PATCH SCRIPSIT/XMT {A=89E1,F=61,C=63}
PATCH SCRIPSIT/XMT {A=EF20,F=64,C=65}
PATCH SCRIPSIT/XMT {A=8A05,F=64,C=65}
PATCH SCRIPSIT/XMT {A=E9C7,F=64,C=65}
PATCH SCRIPSIT/XMT {A=E9F4,F=41,C=42}
```

If these OPTIONAL PATCHES are applied, a notation should be made in the Version Log; however, the Version number will remain 01.00.00 after applying these PATCHES.