

CUSTOMER SERVICE BULLETIN

Radio Shack® CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	4831-04
Description	SCRIPSIT HD
Model	Model II
Stock No.	26-4831 Vers. 01.00.03
Date	June 1, 1983
Page 1 of	1

Problem

Line spacing is not being recalled properly when a document is opened after setting default for double line spacing, creating document, exiting, and returning to the same document. Starting a new paragraph causes the line spacing to change to single spacing.

* * THE FOLLOWING PATCHES ARE REQUIRED! * *

Solution

To correct the problem, apply the following patches.

```
PATCH SCRIPSIT/SYS R=167 B=205 F=2110000 C=CD11DB
PATCH SCRIPSIT/CMD A=DB11 F=2020202020 C=3AF032326E
PATCH SCRIPSIT/CMD A=DB16 F=2020202020 C=90211000C9
```

To change the version number, apply the following patch.

```
PATCH SCRIPSIT A=E2E3 F=33 C=34
```

After patches from this Bulletin have been applied, the version number will be 01.00.04. Please make the necessary entry in your Version Log.