

# CUSTOMER SERVICE BULLETIN

## Radio Shack® CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

<b>Bulletin No.</b>	4831-01
<b>Description</b>	SCRIPSIT-HD
<b>Model</b>	Model II
<b>Stock No.</b>	26-4831 Vers. 01.00.00
<b>Date</b>	April 6, 1983
<b>Page 1 of</b>	1

### Problem

Scripsit-HD won't print multiple copies when doing a merge.

\* \* THE FOLLOWING PATCH IS REQUIRED! \* \*

### Solution

To correct the problem, apply the following patch to the installed version and to the installation diskette.

PATCH SCRIPSIT/SYS R=195 B=188 F=22808A C=000000

Apply the following patch to change the version number.

PATCH SCRIPSIT A=E2E1 F=202020 C='.01'

After patches from this Bulletin have been applied, the version number will be 01.00.01. Please make the necessary entry in your Version Log.