

FREHD CABLE INSTALLATION MODEL III OR MODEL 4 NGA WITH SERIAL BOARD INSTALLED

1. Cut out the **2nd rib** on the bottom of the case (**FIGURE 1**)
2. Place the cable with the **RED STRIPE** facing **LEFT** (**FIGURE 2**)
3. Attach the cable to the connector (**FIGURE 3**)
4. Route the cable (**FIGURES 4,5,6**)
5. To use frehd
 1. Turn on system - frehd should blink green one time
 2. Insert SD card in slot - frehd should blink green one time
 3. At "Diskette?" prompt **PRESS THE RED RESET BUTTON** - frehd should boot

