

# CUSTOMER SERVICE BULLETIN

## Radio Shack® CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	1917-01
Description	BEDLAM
Model	Model I/III
Stock No.	26-1917 Version 1.0
Date	August 9, 1982
Page 1 of	1

### Problem

There is a misprint in the Owner's Manual (page 6) in the portion of the instructions that explain how to modify the program for Model I Disk use.

\* \* \* THIS LINE CHANGE IS REQUIRED! \* \* \*

### Solution

1. Make the following change to the line below which is listed near the bottom of Page 6 in the manual.

OLD LINE: DUMP BEDLAM/CMD (START=X'8020',END=X'0BD3F',TRA=X'0BD30')

NEW LINE: DUMP BEDLAM/CMD (START=X'8020',END=X'0BD6F',TRA=X'0BD30')