Radio Shack
A Division of Tandy Corporation

NATIONAL FRANCHISE OFFICE 817-390-3605
1000 ONE TANDY CENTER, FORT WORTH, TEXAS 76102

MEMO

To: All Franchise & ASC Stores
From: Vicki Knight
Date: January 31, 1985
Subject: RSC-14 Clarifications and Corrections

Following are the corrections to RSC-14:

p. 6 The correct stock number for Videotex Plus is 25-1150.

p. 8 The text states "Now get 256K memory at $300 less than last year." It should state "$550 less". This reflects the new low price on the Tandy 2000 plus the inclusion of 256K RAM, which was a $299 value in RSC-12.

p. 9 Add the following information: 26-5160 Internal 128K RAM Kit. This item is available at $299.

p. 11 26-5304 Symphony requires 512K RAM.

p. 15 25-3044 Graphics Master provides 640 x 400 monochrome. It provides 640 x 200 4-color graphics with the CM-2. The board does support 640 x 400 color graphics, but not with the CM-2 monitor. This would only be the case with more expensive monitors from other sources.

p. 15 25-3170 WordStar Professional has been recently reworked so that warehouse stock runs on the Tandy 1200/2000/1000. Those packages which run on all machines are noted with a sticker on the box.

p. 16 The specifications lists a 35-megabyte hard disk. It should read "15-megabyte hard disk".

p. 17 26-1198 Parallel-to-Serial Converter. This should read Serial-to-Parallel Converter.

p. 29 26-1122 Model 4 64K RAM Kit. This kit may also be used to upgrade from 16K to 64K.

p. 29 26-1164/1161 External Disk Drives. These also work as an extra drive for Model I owners.

p. 30 26-1544 Invoice Writer. Add the following information: This program interfaces with 26-1545 Inventory Control System.

(SEE REVERSE SIDE)

Radio Shack
A Division of Tandy Corporation
NATIONAL FRANCHISE OFFICE 817-390-3605
1000 ONE TANDY CENTER, FORT WORTH, TEXAS 76102

p. 30 26-1545 Model 4 Inventory Control. The "F" code is incorrect. The program requires three floppy drives. Also, a hard disk is required to run this on a 4P.

p. 32 26-1527 Formation. This program runs on the Model 4/4P.

p. 33 26-2025 Construction Estimator. This program runs on the Model 4/4P.

p. 36 26-1919 Magic Carpet. The "1/2" code is incorrect. The program loads only on a Model III. (Code 2)

p. 39 26-1241 General Purpose Standard Cards. The cards are 40 column with timing marks.

p. 42 26-2114 Sourcebook, Volume 6. The catalog price of $7.95 is correct. (The price book lists an incorrect price.)

p. 45 26-3253 Color Disk Profile does not support password protection.

p. 48 26-3103 Color File. The sample printout shows two columns of data, but the program only prints single columns.

p. 48/49 26-3121/3077 Color Screen Print Utility/Micropainter. The utility works with screens generated by Micropainter but not with Graphics Pak or Art Gallery.

p. 51 26-1193 FP-215. The paper size listed is 8 x 11½. It should be 8½ x 11.

p. 57 26-1189 BPS-400. The text "not for use with...any system with AC motors" is referring to disk drives.