Radio Shack COMPUTER TECHNICAL SUPPORT 0220 817-390-3969
400 ATRIUM — ONE TANDY CENTER, FORT WORTH, TX 76102

DATE: 02/25/1982

TO: Users of the Model II/12 Diagnostic Disk AXX-2034

FROM: Technical Support

SUBJECT: Patch to the 8" TDC program and FDCALG

Before Using TDC, please apply the following patch. This patch will change the drive type prompt from 0-2 to 0-3.

PATCH TDC A=32D5 F=32 C=33

Before using the program FDCALG the following two patches should be applied.

PATCH FDCALG A=328F F=66 C=FF

PATCH FDCALG A=34F1 F=31 C=32

The first patch changes the data pattern from 66 to FF during the data separator adjustment for early version FDC boards. The second changes the version number from 2.1 to 2.2.