

# PERCOM VECTORGRAM


Att: Atari Retailer

From: Dixie Dowlen  
Manager of Special Sales

## PERCOM'S SEPARATOR: A SOLUTION TO ATARI 810\* DISK DRIVE PROBLEMS

Owners of Atari's 810 mini-disk system are plagued with read-data problems (ERROR 138, 144).

The Percom SEPARATOR virtually eliminates these problems.



Developed for the TRS-80† computer, the Percom SEPARATOR substitutes an improved, reliable data/clock separator for the separator circuit used by the host system. Thousands of SEPARATORS have been installed by TRS-80 computer owners, who report that it is a virtual cure-all for disk read problems.

The SEPARATOR may also be used on the Atari 810 disk system with similar results.

Installation is simple. The 1771 IC is removed from the host disk controller card and plugged into the SEPARATOR. Then the SEPARATOR is plugged into the vacated 1771 socket.

The suggested retail price of the Percom SEPARATOR is \$29.95. In order to introduce you to Percom's fine line of quality products, I can make you a one-time offer, good through February 1982, to purchase SEPARATORS at \$19.50 each, in quantities of 10 minimum.

To place an order, call me, Dixie Dowlen, at 1-800-527-1222 (from Texas call (214) 340-7981).

A Percom SEPARATOR is a great way to convert an unhappy Atari owner into a satisfied customer -- for a very small investment.

PERCOM and SEPARATOR are trademarks of Percom Data Company, Inc.

\* Trademark of Atari Corporation.

† Trademark of Tandy Radio Shack Corporation which has no relationship to Percom Data Company.

