

CUSTOMER SERVICE BULLETIN

Radio Shack® CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	1502-1
Description	In Memory Information
Model	Model 1
Stock No.	26-1502 Version 1.0
Date	June 21, 1978
Page 1 of	1

Problem

To use the IN-MEMORY INFORMATION SYSTEM with the 32K and 48K system, the following additional steps are required before the programs are run.

Solution

INITIALIZATION

1. Load the program under the SYSTEM mode.
2. After the program has loaded and the computer prompts you with '*?', press BREAK and return to BASIC.
3. Type the following: POKE 17607,218 and press ENTER.
4. Return to the SYSTEM mode and type '/17280', followed by <ENTER>. This will start the program.

RETRIEVAL & UPDATE

Same as above, except in Step 3. Type: POKE 17894,218

CUSTOMER SERVICE BULLETIN

Radio Shack® CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	1502-1
Description	In Memory Information
Model	Model 1
Stock No.	26-1502 Version 1.0
Date	June 21, 1978
Page 1 of	1

Problem

To use the IN-MEMORY INFORMATION SYSTEM with the 32K and 48K system, the following additional steps are required before the programs are run.

Solution

INITIALIZATION

1. Load the program under the SYSTEM mode.
2. After the program has loaded and the computer prompts you with '*?', press BREAK and return to BASIC.
3. Type the following: POKE 17607,218 and press ENTER.
4. Return to the SYSTEM mode and type '/17280', followed by <ENTER>. This will start the program.

RETRIEVAL & UPDATE

Same as above, except in Step 3. Type: POKE 17894,218